TVC/HI A FMEA NO. 4.3.6.1 SHUTTLE CCTV DMG NO. 2294819-506.508/ CRITICAL ITEMS LIST 2307008-503 CRITICACTLY \_\_2/2\_ SHEEL ÛF FAILURE HODE AND FAILURE EFFECT CAUSE ON END 11tm RATIONALE FOR ACCEPTANCE Lens mation functions, zoom, facus, Inability to control DESIGN FEATURES and iris, do not respond to locus, zvom, or iris. commands (electrical failure). The TVC/Lens Assembly is comprised of 16 electrical subassemblies: 13 subassemblies Morst Tase: are PCA Astro designed and fabricated using standard printed-circuit board type of loss of mission critical construction. The remaining three assemblies, high voltage power supply, oscillator, Stepper Hutar Drive. vi∂ea. and stepper motors, are vendor supplied components which have been specified and 2294880 504 purchased according to RCA Specification Control Brawings (SCDs) prepared by engi-Power Supply. nearing and reliability assurance. Specifications per the SCD are prepared to Cummand Receivers. establish the design, performance, test, qualification, and acceptance requirements 2294881-501 for a procured piece of equipment. Parts, materials, processes, and design guidelines for the Shuttle CETV program are specified in accordance with BCA 2295503. This document defines the program requirements for selection and control of EEE parts. To the maximum extent, and consistent with availability, all parts have been selected from military specifications at the JAN level, as a minimum. In addition to the overall selection criteria, a subset of general purpose preferred parts has been defined by this document and the REA Government Systems Division Standard Parts List. In the case of the CMOS and I'll family of microcircuits, devices are screened and tested to the MIL-SID-BOSC equivalent and procured under the designations of HI-REL/3HQ and SNC 54LS from RCA-SSD and lexas Instruments Corp, respectively. Parts not included in the above documents have been used in the design only after a nonstandard item approval form (NSIAF) has been prepared, submitted to Reliability Assurance Engineering (RAF) and approved for use in the specific application(s) defined in the MSIAF by MASA-JSC. Worst-Case Circuit Analyses have been performed and documented for all circuit designs to demonstrate that sufficient operating margins exist for all operating conditions. The analysis was worst case in that the value for each of the variable parameters was set to limits that will drive the output to a maximum (or minimum). A component application review and analysis was conducted to verify that the applied stress on each piece part by the temperature extremes identified with environmental qualification testing does not exceed the stress denating values identified in RCA In addition, an objective examination of the design was performed through a PDR and CDR to verify that the IVE/Lens ascembly met specification and contractual require-

FMLA	NO.	4.3.6.1

CRITICALITY 2/2

SHUTTLE CCTV CRITICAL LIENS EIST UNIT <u>FYC/WLA</u>
DHG NO. 2294819-506.508/
2107088-503
SHEET 2 OF 9

FAILURE MODE AND

tens motion functions, zoom, facus, and tris, do not respend to commands (electrical failure).

NI.A

A! Stepper Mater Drive. 2294080-504

A2 Power Supply. Command Receivers. 2294881-501 FAILURE EFFECT
ON END IJEM

Instillity to control focus, zoon, or iris.

Horst Case: Loss of mission critical video. DESIGN FEATURES (Continued)

BARE BUARD DESIGN (A2)

The design of the associated A2 board is constructed from laminated coppercial epoxy glass sheets (MEMA G-ND) Grade FR-4), PER MEL-P-55617A. Eircuit connections are made through printed traces which run from point to point on the board surfaces. Every trace terminates at on annular ring. The annular ring surrounds the hole in which a component lead or terminal is located. This ring provides a footing for the solder, ensuring good mechanical and electrical performance. Its size and shape are governed by MEL-P-55640 as are trace widths, spacing and routing. These requirements are reliterated specifically in drawing mates to further assure compliance. Variations between the artwork master and the final product (due to irregularities of the etching process) are also controlled by drawing notes. This prevents making defective boards from good artwork, Holes which house no lead or terminal, but serve only to electrically interconnect the different board layers, contain stitch bars for mechanical support and increased reliability.

BALLONALE FOR ACCEPTANCE

The thre heles are drilled from a drill tape thos eliminating the possibility of human error and allowing tight control over hole and annular ring concentricity, an important reliability criterion. After drilling and etching, all support cladding is tin-lead plated per MIL-SIO-1495. This provides for easy and reliable soldering at the time of board assembly, even after periods of prolonged storage.

BOARO ASSEMBLY DESIGN (A2)

All components are installed on a manner which assures maximum reliability. Component leads are pre-tinned, allowing total metting of sulder joints. All leads are furmed to provide stress relief and the bodies of large components are staked. Special mounting and handling instructions are included in each drawing required after final assembly. The board is coated with urethane which protects against humidity and contamination.

BOARD PLACEMENT (A1, A2)

The Al and A2 boards are secured in the electronics assembly by gold-plated beryllium copper card guides. Connections are made to the mother hoard with blind-maled connectors. Disengagement during launch is prevented by a cover which spans the board's free edge.

IMIA NO. 4.3.6.1 CRECICALITY 2/2		SHUTTLE CCTV CRITICAL TEENS 115T	UNIT IVC/HLA  DWG NO. 2294819-506.508/ 2307008-503  SHEET 3 OF 9
TAILURE WHIF AND  COUNTY COMMITTEE THE STATE OF THE STATE	FAILURE EFFECT ON END TIEM Inability to control. focus, zoom, or tris.  Worst Case: Loss of mission critical video.	PESIGN FEATURES (Continued)  BARE DOARD CONSTRUCTION (A1)  The board is of "webded wire" construction. At the b distinguish it from a normal PC board except that hal generally are not connected to PC traces. Only those ground potentials to the ICs are on PCs. An annular board where each power and ground pin is located. In the trace like any other component lead. Aside from a construction techniques used in PC board layout app BOARD ASSEMBLY (A1)  The drilled and etched board is populated with several webdable pins. Power and ground pins, as well as conplace. Discreet components (resistors, digdes, capace bifurcated terminals, where they are soldered. Fistp lead-by-lead to the tops of the weld pins. After well trimmed away. Circuit connections are made using 3d wire is welded to the pin surfaces on the board backs using a machine which is tape driven, thus eliminating due to operator error. All wiring a circuit performation-level installation. After successful testing, could be board is inserted in the box on card-edge guides. PC boards.	are board level this does not es which will take weld pins pins which bring power and ring surrounds the hole in the ese pins are then soldered to this feature, all design ly.  I hundred solderable or nector pins, are soldered in iters) are attached to ack ICs are welded, ding, extra lead material is AMG nickel weld wire. The ide. All wire welds are done githe possibility of miswiring nee is tested prior to mponents are staked as required hane.

FREA NO. 4.3.6.1		SHUTTLE CCTV CAITICAL ITEMS LIST	UNIT OHG NO. SHEET _	IVC/WLA 229:1019:506 230/080-503 _4 OF	.508/
FAITURE HODE AND  CAUSE  ens motion functions, zoon, focus, and vris, do not respond to commands (e)ectrical failure).  (A Stepper Mutur Drive. 2294880-504 (C Power Supply. Command Meceivers. 2294001-50)	FAILURE EFFECT ON END TIEM Inability to control focus, zoon, or iris. Herst Case: Loss of mission critical video.	RATIONALE FOR ACCEPTANCE  QUALIFICATION TESTS  for Qualification Test Flow, see Table 2 located at the	frant of L	his book.	
• ·		·			
					•

		1		
THEA NO. 4.3.8.1  CRETICALITY 2/2		. CR	SHUTTLE CCTV STICAL STEMS LIST	UNIT 19C/HLA DHG HU. 2294819-506.500/ 2307088-503 SHEET 5 OF 9
FAILURE HODE AND CAUSE	FAILURE EFFECT UN END LIEN		RATIONALE FOR ACCEPTANCE	
Lens motion functions, zoom, focus, and iris, do not respond to commands (electrical failure).  HIA Al Stepper Motor Orive. 2294880 SD4 AZ Power Supply. Command Receivers. 2294883-50)	Inability to control focus, zoom, or iris.  Horst Case: Less of mission critical video.	ACCEPLANCE ):SI  The CCTV systems' we be used in their and   • Vibration:	AtA is subjected directly, without viormal installation, to the following  20-80Hz: 3 dB/05t-rise from 80-350 Hz: 0.04 GF/Hz 350-750 Hz: -3 dB/10 Ort-slope Test Duration:   Hinute per Axis Test Level: 6.1 Grms	testray: D.OI G <sup>2</sup> /Hz
		• Thermal Vacuum;	In a pressure of IX10 <sup>-5</sup> form, the t follows: 125° f: Time to stablize equipment 25° f: Time to stablize equipment 125° f: Time to stablize equipment	plus I kaur
		The HLA may not have	e been subjected to the vacuum condi	
		For Acceptance lest	flow. See lable I located at the fre	ent of this book,
		OPERALIONAL TESTS		
		through the RCU, the decuder. The test ability to route vi	that CCIV components are operational ommand related components from the P rough the sync lines to the Camera/P Must also verity the camera's abilit deo, and the monitor's ability to do to verify the MON command path.	NO TAVATT panel switch. TV, to the Camera/PSV command
		Pre-Launch, on 1	Orbiter Test/la-flight Test	
		3. Send "Camer 4. Select "Ent 5. Observe via 5 ynchroniza is receivin 5 ynchroniza 6. Send Pan, in 7. Select dawn 6. Hasrave via 9. Send "Camer 10. Repeat Step	S panel, select a monitor as destinature.  ra Power On" command from PHS panel.  Lernal Sync" on monitor. Mute that  deo displayed on monitor. Mute that  ed (i.e., stable raster) then this is  ng composite sync from the RCV and tr  ed videg.  Lilt focus, Znom, DtR, AND Gamma com  nitor or direct observation) versty o  clink as destination and camera under  led routed to downlink.  Tower DtF command via PHS panel.  S 3 through 0 except issue command.	if video on munitor is odicates that the camera not the camera is producing mands and visually (either operation.
4lik		Hirs proves	that the ECIV equipment is operation	via the mumicand path. Dal-

			REV[SED 10-14-
EMITA NO. 43.6.3 CATTICALITY 2/2		SHUTTLE CCTV CRITICAL TIEMS LIST	UNIT IVC/VLA  DWG NO. 2294819-506,508/ 2307088-503  SHEEF 6 OF 9
FATIURE MIDE AND CAUSE	FAILURE EFFECT	RATIONALE FOR ACCEPTANCE	
tens motion functions, zoom, focus, and iris, do not respond to commands (electrical failure).  HLA Al Stepper Motor Drive. 2294680-504 AZ Power Supply. Command Receivers. 2294683-501	Inability to central facus. 200m, or iris.  Warst Case: Loss of mission critical video.	Procurement Control - The TVC/NLA EEE Parts and hardware approved vendors and suppliers, which meet the requirement contract and Quality Plan Hork Statement (WS-2593176), review all procurement documents to establish the need (PAL 517).  Incoming Inspection and Storage - Incoming Quality inspeceived materials and parts. Results are recorded by drawing and control numbers for future reference and trare subjected to incoming acceptance tests as called for Inspection Test Instructions. Incoming flight parts are accordance with REA 1846684 - Preconditioning and Accept Electronic Parts, with the exception that OPA and PIND Mechanical items are inspected per PAL 316 - Incoming I mechanical items, PAL 305 - Incoming Quality Control for PAL 512 - Procedure for Processing Incoming or Purchase flight Use. Accepted items are delivered to Haterial C retained under specified conditions until Fabrication i materials are held for Material Review Board (MRB) dispipal IQC 531).  Board Assembly & Pest - Prior to the start of MLA mound to be correct by stock room personnel, as the items are items are verified again by the operator who assembles as-built-parts-list (ABPL). DEAS Nambatory Inspection in printed circuit, wire weap and welded wire thards, plusing wiring, crimping, solder splices and quality workman compunent side of boards and sleeving of harnesses. Spin assembly drawing notes and applicable documents called and record (IPR-2307088) and Parts list PL 2307088. The 2303349, Nutes - wide angle zoom lens assy 2303191, Propotting, encapsulating 2280878, Specification - Urethand Morkmanship Spec 8030035.  IVE Assembly and Içst - An open box test is performed parts and parts and part	e items are procured from ents set forth in the CCIV Resident OCAS personnel for GSL on selected parts ections are made on all lot and retained in file by aceability. All EEE parts r in PAL 115 — lacoming e further processed in tance Requirements for testing is not performed. Aspection Instructions for spection Instructions for spection Instruction, and A Parts Designated for outrolled Stores and s required. Non-conforming osition. (PAL 307,  assembly, all items are verified accumulated to form a kir. The the kit by checking against the Points are designated for all harness connectors for solder—oship prior to coating of the ecific instructions are given in out in the labrication procedure se include wire connection list cass Standard — bundang staking, a protective coating 2200077 and

ance lest per IP-AI-2294819, including vibration and thermal vacuum. Torques are specified and witnessed, traceability numbers are recorded and calibrated tools are checked prior to use. RCA Quality and DCAS inspections are performed at the completion of specified FPH operations in accurdance with PAT 204, PAT 205, PAT 206 and PAT 217.

DCAS personnel witness IVE button-up and critical torquing.

<u></u>			REVISED 10-14-
FMEA NO. 4.3.6.1  CRETICALLY 2/2	<u> </u>	SHUFFLE COTY CRITICAL ITEMS EIST	UNIT TVC/HEA  DWG NO. 2294819-506-508/ 2307088-503  SHEET 7 00 9
FAILURE MODE AND CAUSE less motion functions, zoom, focus, and iris, do not respond to commands (electrical failure).  MLA At Stepper Motor Drive. 2294880-504 At Power Supply. Command Receivers. 2294881-501	FAILURE EFFECT ON END [[EM Inability to control tocus, zoom, or iris.  Horst Case: Loss of mission critical video.	QA/INSPECTION (Continued)  WIA Assembly and Icst — An open box test is performed the prior test per IP-AT-2107088. Torques are specified and recorded and calibrated tools are checked prior to tions are performed at the completion of specified PAI 204, PAI 205, PAI 217 and PAI 472. DCAS perso critical turquing.  IVC/VIA Assembly and Icst — After a IVC and a WIA they are mated and a final acceptance test is perforbination and thermal vacuum environments. REA and tests and review the acceptance test data/results. after all repair, rework and retest.  Preparation for Shipment — The IVC and HIA are septiable fabrication and testing is complete. Each is packed and 228074b, Process standard for Packaging and Hadder and held in a documentation folder assign This tolder is retained for reference. An EIDP is accordance with the requirements of W5-2593176. Recrating, packaging, packing and marking, and review accuracy.	med per TP-11-2307088, Acceptance I witnossed, traceability numbers are ouse. RCA Quality and DCAS inspec- I FPR operations in accordance with nonel witness WLA button-up and have been tested individually, ormed per TP-AI-2294Biy, including d DCAS personnel monitor these These personnel also inspect arated prior to shipment after aged according to CCTV Letter 8011 ndling guidelines. All related ist, ABPL. Test Data, etc., is ed specifically to each assembly, prepared for each assembly,
			•

REVISED 11-3-86

THEA NO. 4.3.G.1  CRITICALITY 2/2		SHUTTLE CCTV CRITICAL LIENS LIST	UNIT <u>TVC/MLA</u> ONG NO. <u>2294819-506.508/</u> 2307088-503 SHEET <u>8</u> OF ' <u>9</u>
FAILURE MODE AND  (AUSE  Lens motion functions, zoom, focus, and iris, do not respond to commands (electrical failure).  VIA  Al Stepper Mutor Drive. 2294808-504  Al Power Supply. Command Receivers. 2294881-503	FAILURE EFFECT ON END 11FM Inability to control focus, 200m, or tris.  Norst Case: Loss of mission critical videa.	FAILURE HISTORY  TOR W-1779 L Y-9283, Log #0794 L 0777, MLA S/N 005-503.  Description: Flight Failure, Spacecraft Level. 2 way through its travel. Returned from STS-8.  Cause: Vendor analysis indicated room part deform from reaching its long local length.  Corrective Action: All evidence indicates this for undetermined origin. Defective lens returned installed and Box was subjected to and passed according to the second passed pa	7005-501  DOM-in function stalls at -5° half  Med. This prevented the lens  Dilure to be an isolated instance  TO ANGENIEUX (or repairs, new lens

A . Y . A.

SHUTTLE CCIV CRITICAL TIEMS LIST  FAILURE FIFECT CRITICAL THEMS LIST  FAILURE FIFECT  MICRO THEMS LIST  FAILURE FIFECT  MICRO THEMS LIST  FAILURE FIFECT  WHITE THEMS LIST  FRAITURE FIFECT  FRAITURE FIFECT  FRAITURE FIFECT  SHET THEMS LIST  FRAITURE FIFECT  S				8EVISED 18-14-8
CAUSE tens mation functions, zapm, focus, and fres, do not respond to convenient (electrical failure).  HIS Stepper Motor Drive. 2294880-504 AF Power Supply. Command Receivers. 2294881-501  CREW ACTIONS  CREW TRAINING  Crew should be trained to use possible alternates to CCTV.  MISSION CONSTRAINI  Where possible, procedures should be designed so they can be accomplished without			SHUTTLE CCIV CRITICAL ITEMS LIST	DMG NO. 22 <u>94819-506,5ра/</u> 2307088-503
	CAUSE	ON_END 174M Inability to control focus, 200m, or iris, Worst Case: Loss of mission critical	OPERATIONAL IFFECTS  Video is unusable. Possible loss of major missio required.  CREW ACTIONS  If possible, continue RMS operations using alternates CREW IRAINING  Crew should be trained to use possible alternates MISSION CONSTRAINT  Where possible, procedures should be designed so the	n objectives if RMS elbow camera is ative visual cues.